DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001910 Address: 333 Burma Road **Date Inspected:** 26-Mar-2008

City: Oakland, CA 94607

OSM Arrival Time: 1800 **Project Name:** SAS Superstructure **OSM Departure Time:** 730 Prime Contractor: American Bridge/Fluor Enterprises, a JV

Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Contractor: Location:** Shanghai, China

CWI Name: CWI Present: Yes Chen Chih Ming No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Oualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A **Approved Drawings:** Yes No N/A **Approved WPS:** Yes No **Delayed / Cancelled:** Yes N/A No

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Mike Hasler was present to observe the fitup, welding and related activities associated with the fabricating of Caltrans Mock-up, 77M, 89M, 114M, Orthotropic Box Girders (OBG) and Tower, for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

WBS Item Description Status Dwg No.

Side Panels NA NA Work in Progress.

New OBG Building: Caltrans QA observed ZPMC performing root face weld build up (butter-up) at location identified for excessive root opening. The plate assemblies are identified as subassembly SP018-001 splice weld joining SP026-001 and SP009-001 splice weld joining SP008-001. It appeared that ZPMC has completed the welding portion of the butter-up and is in the process of performing weld prep by grinding the butter-up weld to a smooth uniform surface.

Caltrans QA Inspector observed flux cored arc welding (FCAW), complete joint penetration (CJP) plate splice weld, fill pass weld. The subassembly identified as skin plate SP57B to SP45B. The welder operator is identified as Mr. Gao Dong Liang, welder stamp 048714. The welder is using welding procedure specification WPS-B-T-223 (2) 1T. Caltrans QA measured current welding parameters at approximately 290 amps, 29.5 volts and 200mm/min (millimeters per minute) travel speed. Preheat and interpass temperatures were verified during welding activities. The preheat temperature prior to the start of welding measures more than 69 degrees Celsius but less than 230 degrees Celsius during maximum interpass temperature verification. Caltrans OA observed ZPMC Quality Control (QC/CWI), Mr. Chen Chih Ming monitoring the welding activities at the work-station. The following digital picture illustrates the welding of splice weld, SEG013A-013.


WELDING INSPECTION REPORT

(Continued Page 2 of 3)



NA Deck Panel NA QA VT

OBG Bay 1: Caltrans QA Inspector performed visual inspection of the completed submerged arc welding (SAW) cover pass welds; partial joint penetration (PJP) welds joining the closed ribs to deck plate panel DP191-001, u-rib U103, welds 1 & 2; u-rib U96, welds 3 & 4; u-rib U97, welds 5 & 6, u-rib U110 welds 7 & 8, u-rib U109 welds 9 & 10. Caltrans QA observed welding overlap, over size welds, underfill and incomplete fusion. These indications observed at the weld were marked in yellow paint stick along the distance from the "Y" axis, starting at the weld start too weld completion end. The weld indications observed were recorded on Caltrans spreadsheet for future reference. The following digital pictures illustrate DP191-001 deck panel and typical incomplete fusion indications.





Summary of Conversations:

As identified within the contents of this report.

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Patrick Lowry, (858) 344-2712, who represents the Office of Structural Materials for your project.

Inspected By: Hasler, Mike Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Reviewed By: Cuellar,Robert QA Reviewer